
- Instructions d'assemblage **Boîtes de distribution AK II**
- Instrucciones de montaje




- Cajas de distribución AK II

₽

70610201

- Lösen der Normschiene
- Removal of the mounting rail Détachement des barres normées Desmontaje del carril de la asamblea

- Montageanleitung Kleinverteiler AK II
- Installation Manual **Distribution board system AK II**



Assembly cable cover **Montage Kabelblende**

- Montaje tapa cubre-cables

Adjustment of hinged cover right/left

Umbau Klappdeckel, Rechts/Links

Aménagement du couvercle à


charnière droit/gauche Cambio de la puerta abisagrado/


Montage couverture pour câbles


- Montage Schloßgarnitur/ Schließriegel
- Assembly lockset/ lock rail
- Montage set de fermeture/barre de fermeture Montaje kit de cerradura/cierre corredizo

70610401

- Kombination
- Combination Combinaison








- **Splittung in verschiedene N-Potentiale (ab AK 28)**Partition of the seperate connection terminal plate (starting with AK 28)
 Partition de la borne separée (dès AK 28)

- Partición de la barra de terminales separada (desde AK 28)



<u>els</u> spelsberg

Im Gewerbepark 1
D-58579 Schalksmühle
Telefon: 49 (0)2355/892-0
Telefax: 49 (0)2355/892-299
e-mail: info@spelsberg.de
Internet: www.spelsberg.de

Günther Spelsberg GmbH + Co. KG